


L2 WINDING: START END GOES UP THROUGHBACK SIDE OF CORE
 CONTINUE WINDING PASSING WIRE DOWN THROUGH HOLE FROM FRONT
 SIDE OF CORE, WINDING IN COUNTER CLOCKWISE DIRECTION.
 AFTER 29 TURNS, MAKE LOOP AND CONTINUE WINDING
 5 MORE TURNS FOR FEEDBACK WINDING.

START OF PRIMARY WINDING
 START OF FEEDBACK WINDING



LONG JUMPER BETWEEN POINTS "A" AND "A"